Lockheed Martin Corporation
6801 Rockledge Drive MP: CCT-246
Bethesda, MD 20817
Telephone 301-548-2209

May 14, 2018 **VIA PRIVATE CARRIER**

Mr. James R. Carroll
Program Administrator
Land RSubject: Transmittal of the Semi-Annual Site Progress Report: November 2017-April 2018

Lockheed Martin Corporation – Middle River Complex
2323 Eastern Boulevard, Middle River, Baltimore County, Maryland
Reference: MDE Case No. ACO-SAR-MDE0746-2015-1-01

Dear Mr. Carroll:

In compliance with the Administrative Consent Order and Settlement Agreement, please find enclosed one hard copy of the above-referenced document. This semi-annual site progress report includes a summary of the major work events and issues noted from November 2017 through April 2018.

Please let me know if you have any questions. My office phone is (301) 548-2209.

Sincerely,

Thomas D. Blackman
Project Lead, Environmental Remediation

cc: (via email without enclosure)
Mark Mank, MDE
Gary Schold, MDE
Christine Kline, Lockheed Martin
Norman Varney, Lockheed Martin
Michael Martin, Tetra Tech
Cannon Silver, CDM Smith

cc: (via mail with enclosure)
Randy Huff, LMCPI
Tom Green, LMCPI

cc: (via Secure Information Exchange)
Jann Richardson, Lockheed Martin
Scott Heinlein, LMCPI
Christopher Keller, LMCPI
Glen Harriel, LMCPI

Major Events and Issues November 2017 to April 2018

1. Groundwater and Surface Water Monitoring
    a. Conducted annual groundwater and surface water monitoring field work in April 2018.

Deliverable	Date Transmitted to MDE	Date Approved by MDE

-.0022 W T c D E (
– Block E/
trichloroe
Addendu

Deliverable	Date Transmitted to MDE	Date Approved by MDE
Groundwater Remedy Blocks E/ F		
Block E Downgradient Trichloroethene Plume Additional Investigation Report	12/15/2017	2/14/2018

ii. Attempted storm drain cleaning at Block E manhole 9.
Problem Encountered: Cleaning was unsuccessful during first attempt in March 2018 due to equipment problems.
Resolution: Returned for second attempt at cleaning in April 2018. Cleaning was successful.

d. Soil Remedial Investigation Block E:
   i. Completed Block E soil remedial investigation field work in November 2017 in fulfillment of Block E Soil Remedial Investigation Work Plan Addendum 3: Fall 2017 Soil and Groundwater Sampling. Reporting associated with this investigation is anticipated to be complete by July 2018.
   ii. Completed pre-RAP design investigation field work in Block E in April 2018 in fulfillment of Addendum 4 Block E Soil Remedial Investigation Work Plan Remedial Action Alternatives Evaluation Data Collection.
   iii. Held meeting with MDE Land Management and MDE Air and Radiation Management on 4/26/18 to discuss how radiological contamination will be handled in the Block E Remedial Action Plan (RAP).

Deliverable	Date Transmitted to MDE	Date Approved by MDE
Soil		
Block H Soil Remedial Action – No Further Action Letter and Environmental Covenant	9/27/2017	Environmental covenant and NFA letter recordation with Baltimore Co. on 2/20/2018; recorded in MDE registry on 4/6/2018
Block D Soil Remedial Action – No Further Action Letter and Environmental Covenant	9/27/2017	
Block D Panhandle Soil Remedial Action – No Further Action Letter and Environmental Covenant	9/27/2017	
Block F Soil Remedial Action – No Further Action Letter and Environmental Covenant	9/27/2017	
Block G Soil Remedial Action – No Further Action Letter and Environmental Covenant	9/27/2017	
Second revised Slag Characterization Report	11/15/2017	12/20/2017
Addendum 4 Block E Soil Remedial Investigation Work Plan Remedial Action Alternatives Evaluation Data Collection	12/13/2017	*
Block E Storm Drain Monitoring Report: PCB Sediment Sampling of Storm Drain Systems for Outfalls 006 and 008		

* Submitted for MDE records and information

7. Vapor
    a. Block I Building A and Building A Basement
        i. Conducted Building A semi-annual vapor intrusion monitoring in Feb. 2018 (Round 24).
        ii. Problem Encountered: Unanticipated shutdown of Building A sub-slab depressurization system (SSDS) for one week in Jan. 2018. Resolution: Conducted subsequent air sampling. Results indicated indoor air remained below screening levels. Report will be submitted to MDE in May 2018.
    b. LMCP Maintenance Building
        i. Completed lab analyses related to 1st sub-slab soil vapor monitoring event in LMCP maintenance building (1st event took place in Oct. 2017). Results to be documented in upcoming Groundwater Monitoring Well and Vapor Monitoring Point Installation Report: Block I Maintenance Building and Surrounding Areas
        ii. Conducted 2nd sub-slab vapor monitoring event in LMCP Maintenance Building in Feb. 2018. Results remain below screening levels.
    c. Continued Buildings A and C SSDS Operation, maintenance and sampling.

Deliverable	Date Transmitted to MDE	Date Approved by MDE
Vapor		
Vapor Intrusion Investigation and Sub-Slab Depressurization System Operation, Round 22, March 2017 Monitoring Report	10/6/2017	11/28/2017
Indoor Air Quality and Sub-Slab Vapor Sampling Work Plan, Rounds 24 through 29, Buildings A, B and C	12/11/2017	2/1/2018
Vapor Intrusion Investigation Round 13 – February 2017 for Tilley Chemical	1/23/2018	*
Vapor Intrusion Investigation and Sub-Slab Depressurization System Operation Round 23 August 2017	3/1/2018	4/12/2018

* Submitted for MDE records and information

Attachments:

Exhibit A. Property Parcels Map (updated based on Environmental Covenants / No Further Action recorded in April 2018)

Exhibit B. Workplans/Reports Representing Completed and Approved Site Investigation Work

Exhibit C. Workplans/Reports Representing Completed and Approved Remedial Action Plans

Exhibit D. Remedial Action Objectives Status Summary

EXHIBIT A - PROPERTY PARCELS MAP

EXHIBIT B - WORKPLANS/REPORTS REPRESENTING COMPLETED AND APPROVED SITE INVESTIGATION WORK