

Quality Requirements
Q4R - Foreign Object Debris/Damage Prevention

=====
Notice: A hard copy of this document may not be the document
currently in effect. The current version is always the
version on the Lockheed Martin network.

- A. Seller shall develop and maintain a Foreign Object Debris/Damage ("FOD") Prevention program including the engineering design process and controls at manufacturing areas to prevent introduction of foreign objects into any item delivered under this purchase order ("PO").
- B. Seller shall employ appropriate housekeeping practices to assure timely removal of residue/debris generated, if any, during manufacturing operations and/or normal daily tasks. Seller shall determine if sensitive areas that may have a high probability for introduction of foreign objects should have special emphasis controls in place appropriate for the manufacturing environment.

Seller shall determine the need for, and implement, FOD Prevention awareness training programs.